

C.L. "BUTCH" OTTER – Governor RICHARD M. ARMSTRONG – Director

DEBBY RANSOM, R.N., R.H.I.T – Chief BUREAU OF FACILITY STANDARDS 3232 Elder Street P.O. Box 83720 Boise, Idaho 83720-0036 PHONE: (208) 334-6626 FAX: (208) 364-1888 E-mail: fsb@idhw.state.id.us

June 7, 2007

Robert Heberer, Administrator Wellspring Meadows Assisted Living 9873 North Buttercup Lane Hayden, ID 83835

License #: RC-823

Dear Mr. Heberer:

On May 10, 2007, a life safety code survey was conducted at Wellspring Meadows Assisted Living - Wellspring Meadows, Inc.. As a result of that survey, deficient practices were found. The deficiencies were cited at the following level(s):

• Non-core issues, which are described on the Punch List, and for which you have submitted evidence of resolution.

This office is accepting your submitted evidence of resolution.

Should you have questions, please contact Taylor Barkley, Health Facility Surveyor, Facility Fire, Life Safety, and Construction Program, at (208) 334-6626.

Sincerely,

TAYLOR BARKLEY

Team Leader

Health Facility Surveyor

Facility Fire Safety & Construction Program

TB/sc

c:

Mark Grimes, Supervisor, Facility Fire Safety & Construction Program



C.L. "BUTCH" OTTER, Governor RICHARD M. ARMSTRONG - Director DEBBY RANSOM, R.N., R.H.I.T - Chief BUREAU OF FACILITY STANDARDS 3232 Elder Street P.O. Box 83720 Boise, Idaho 83720-033 PHONE: (208) 334-6626 FAX: (208) 364-1888 E-mail: fsb@idhw.state.id.us

May 15, 2007

Robert Heberer, Administrator Wellspring Meadows Assisted Living 9873 North Buttercup Lane Hayden, ID 83835

Dear Mr. Heberer:

On May 10, 2007, a life safety code survey was conducted at Wellspring Meadows Assisted Living - Wellspring Meadows, Inc. The facility was found to be providing a safe environment for its residents.

The enclosed form, stating no core issue deficiencies were cited during the survey, is for your records only and need not be returned.

Please bear in mind that non-core issue deficiencies were identified on the punch list, a copy of which was reviewed and left with you during the exit conference. The completed punch list form and accompanying evidence of resolution (e.g., receipts, pictures, policy updates, etc.) are to be submitted to this office by June 9, 2007.

Should you have any questions about our visit, please contact me at (208) 334-6626.

Sincerely,

MARK GRIMES

Supervisor

Facility Fire Safety & Construction Program

MG/slc

Enclosure

Bureau of Facility Standards (X3) DATE SURVEY STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION COMPLETED AND PLAN OF CORRECTION IDENTIFICATION NUMBER: A. BUILDING 01 - BUILDING 1 B. WING 05/10/2007 13R823 STREET ADDRESS, CITY, STATE, ZIP CODE NAME OF PROVIDER OR SUPPLIER 9873 NORTH BUTTERCUP LANE WELLSPRING MEADOWS ASSISTED LIVING **HAYDEN, ID 83835** PROVIDER'S PLAN OF CORRECTION SUMMARY STATEMENT OF DEFICIENCIES (X5) ID (X4) ID (EACH DEFICIENCY MUST BE PRECEDED BY FULL (EACH CORRECTIVE ACTION SHOULD BE COMPLETE PREFIX PRÉFIX CROSS-REFERENCED TO THE APPROPRIATE DATE REGULATORY OR LSC IDENTIFYING INFORMATION) TAG TAG DEFICIENCY) 5/30/07 Simples Grand was R 000 R 000 Initial Comments abanded, came to facility The facility was found to be in substantial and attached escut cheon compliance with the fire and life safety requirements of the Rules for Residential or Assisted Living Facilities in Idaho. No core deficiencies were cited during the standard fire/life safety survey conducted on May 10, 2007. checked on a monthly The surveyor conducting the survey was: Taylor Barkley Health Facility Surveyor Facility Fire safety & Construction RECEIVED JUN 04 2007 **FACILITY STANDARDS**

Bureau of Facility Standards

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

PHENOR 5-30-0

(X6) DATE



BUREAU OF FACILITY STANDARDS P.O. Box 83720 Boise, ID 83720-0036 (208) 334-6626 fax: (208) 364-1888 ASSISTED LIVING Non-Core Issues Punch List

| | 5 (| |
|------------------------------------|------------------------|--------------|
| Facility Name | Physical Address | Phone Number |
| Wellspring Meadows Assisted LIVING | 9873 N. Buttercup LANE | 208-762-9001 |
| Administrator | City | ZIP Code |
| Jim Heberer | Hayden Id | 83835 |
| Survey Team Leader | Survey Type | Survey Date |
| Taylor Barilley | | 5-10-7 |
| MONLOOPERONIES | | |

| - | leam Leader | | Survey Type | Survey Date | | | |
|-----------------|-------------------|--------------------------------------|--|-------------|--|--|--|
| | TRYLOR | Baritley | | 5-10- | - 7 | | |
| NON-CORE ISSUES | | | | | | | |
| ITEM # | RULE# 16.03.22 | | DESCRIPTION | | DATE BFS RESOLVED USE | | |
| 1 | 405, 05 | The sprinkler head | in the closet by the laundr cutcheon plate, leaving Aga If inch in size. | y 100M | | | |
| | | is missing the es | cutcheon plate, leaving A GA | Ń | | | |
| | | Approximately one ha | If juch In size. | | | | |
| | | | | | | | |
| | | | b | | | | |
| | | | | | 2017 | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | 49.67 | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | 4 (1) (2) (3) (3) (3) (4) (4) (4) (4) (4) (4) (4) (4) (4) (4 | | |
| | | | | | 16 St. 16 | | |
| | | | | | | | |
| | | | | | が ・ | | |
| Dognan | se Required Date | Signature of Facility Representative | | | | | |
| | O - 7 | Signature of Facility Representative | | | Date Signed | | |
| V ((| <u> </u> | | | ····· | 5110107 | | |